

NOTES ON TURVY CHURCH BEFORE
THE RESTORATION 1852-4.

The following notes were started by a curioseity about the position of the old chancel. This led to an examination of the old paintings and drawings near the Font. The C.R.O. photographed these pictures and their descriptions of them provide a degree of interpretation. The situation prior to the extension in 1852-4 would appear to have been as follows:-

The old Chair or Rood screen was on the line of the pillars forming the 3rd. arch from the west end of the nave, this was destroyed in 1804/5, the old chancel then stretched to the east end of the church, level with the Memorial Chapel.

The unfinished sketch by John W Burge in 1834 shows the steps leading to the Altar and the old position of the Font. Also shown are those of the Monadnut Pulpit and to ^{the} left the remains of the Rood Loft. The coloured painting (8501) is a similar view but looking west. Another painting (8494) shows the Chair stalls, the High Altar and the East Window.

One of the most interesting pictures is the fair-black & white drawing of the West end of the Church in 1841. It is difficult to decipher the drawing when from inside the old chancel, as one can see the Chancel Arch, moved during the alterations and the Pulpit and Sounding Board and various Bows. The interesting point is the gallery and what appear to be an organ about the width of the nave and the depth of the first arch. There were originally musicians in the church, thus there is a reference in the Vestry Minutes Churchwarden accounts in 1834-5 for a Bass Bow & String £5.9^d

It seems likely that they originally used the Rood Loft. (see Harvey p. 203), as this finally collapsed a new gallery was built at the West End, possibly to house the Organ

Again in Harvey p. 206 it mentions that the Church was re-pealed in 1846 and in the same year a larger organ was erected in the Western Gallery, Elliott & Hill Builders. In confirmation there is an interesting article from the Northampton Mercury in 1847 about Turney church. It mentions a very large organ with its gallery for performers (causing the people a regular wheeling round of the congregation when they begin). This may have been a factor in the subsequent extension of the church and the rehausing of the organ.
The report on Turney church shows up well against an old Storden church. Turney church had two locks, possibly a precaution against grave-robbers.

Kirk. Oct 90